

Firmware Revision Info:

DMC-34x5 Controller

New feature December 22, 2006 – Rev 1.0d:

- Now new features added

New feature January 5, 2005 - Rev 1.0c:

- Optimized cornering motion profile

New feature September 23, 2003 - Rev 1.0b:

- Added serial port handshake timeout
- Added BK and SL commands to debug user application programs
- Added GA interrogation
- Added AUTOERR special label
- Added _RS operand
- Added RS-1 function
- Reserve 4 SMSC packets for transmits

New feature July 17, 2002 - Rev 1.0a:

- Added support for ioc-7007
- Allow single or dual axis master and slaves
- Allow product to designate a broadcast handle
- Double read of abort, limit and II inputs
- Added option to HC for Command in TCP and QW in UDP
- Abort input on master aborts slaves via ethernet AB command
- Added MW command: wait for modbus response

September 5, 2001 - Rev 1.0

- Initial Release